

SL NO	HMDA LAKE ID	NAME	Mandal & District	Nature of Complaint	Date Initiated/ Reminders	Authorities Responsible	Action Taken	Lat/Long coordinates for HMDA missing lakes	Complaints held up at - Agency
-------	--------------	------	-------------------	---------------------	---------------------------	-------------------------	--------------	---	--------------------------------

1.	3636	Pedda Cheruvu	Saroornagar, RR	CREMATION, DUMPING, SEWERAGE	October 24, 2013	CRD, PS(RD), Collector, MRO, APPCB, HMDA, etc.	NIL		Collector, MRO, HMDA GHMC
2.	3638	Pedda Cheruvu -2	Saroornagar	DUMPING GARBAGE & MUD	October 24, 2013	CRD, PS(RD), Collector, MRO, APPCB, HMDA, etc.			Collector, MRO, HMDA . GHMC
3.	3612	Chandana Cheruvu	Saroornagar	CONSTRUCTIONS IN LAKE BED; ROAD THRU THE LAKE; GIANT WEEDS	October 24, 2013	CRD, PS(RD), Collector, MRO, APPCB, HMDA, etc.			Collector, MRO, HMDA GHMC
4.	3637	Mantrala Cheruvu	Saroornagar	DUMPING; ENCROACHMENT; GIANT WEEDS	October 24, 2013	CRD, PS(RD), Collector, MRO, APPCB, HMDA, etc			Collector, MRO, HMDA
5.	3617	Edugoni Kunta Tank	Saroornagar	PLANTATION INSIDE THE LAKE(TANK CAPACITY AREA); PLANTATION ABOVE RIVETMENT;	REVIVAL PROPOSAL IN 2011	CRD, PS(RD), Collector, MRO, APPCB, HMDA, etc			Collector, MRO, HMDA
6.	3641	Chepala Cheruvu	Saroornagar	PLOTTING IN LAKEBED; SEWERAGE INFLOWS; ROAD THRU LAKE;	October 24, 2013	CRD, PS(RD), Collector, MRO, APPCB, HMDA, etc	Visit by EE-HMDA & DSP-LPC		Collector, MRO, HMDA
7.	3619	Beera	Saroornagar	THREAT OF PLANTATION	REVIVAL	CRD, PS(RD),			Collector,

SL NO	HMDA LAKE ID	NAME	Mandal & District	Nature of Complaint	Date Initiated/ Reminders	Authorities Responsible	Action Taken	Lat/Long coordinates for HMDA missing lakes	Complaints held up at - Agency
-------	--------------	------	-------------------	---------------------	---------------------------	-------------------------	--------------	---	--------------------------------

		cheruvu		AS AT 3617 LAKE	PROPOSAL IN 2011	Collector,MRO, APPCB, HMDA, etc			MRO, HMDA
8.	3602	Umda Sagar	Saroornagar	SEWERAGE INFLOWS; CONSTRUCTIONS IN LAKEBED; ROAD THRU LAKE BED; DUMPING	5.4.2013	CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc			Collector, MRO, HMDA
9.	3601	Jallapalli Talab/ Pedda cheruvu	Saroornagar	CONSTRUCTION OF COLONIES; SEWERAGE INFLOWS; GRAVEYARD; DUMPING; ROAD CONSTRUCTION	5.4.2013	CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc			Collector, MRO, HMDA
10.	3639	Burhan Khan Cheruvu, (Osman Nagar), Guramkani cheeruvu	Saroornagar, RR	ENCROACHMENT BY BUILDING CONSTRUCTION; DUMPING MUD; ROAD CONSTRUCTION; OUTFLOW OF WATER; INFLOW OF LIQUID WASTE;	5.4.2013	CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc			Collector, MRO, HMDA
11.	3609	Yerra Kunta	Saroornagar, RR	BREAKING OF NATURAL BUND; FIR NOT LODGED BY MRO/SHO ;	10.7.2011 25.2.2013 31.12.2013 Lokayukta	CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc	Police seized JCB;		Collector, MRO, HMDA

SL NO	HMDA LAKE ID	NAME	Mandal & District	Nature of Complaint	Date Initiated/ Reminders	Authorities Responsible	Action Taken	Lat/Long coordinates for HMDA missing lakes	Complaints held up at - Agency
-------	--------------	------	-------------------	---------------------	---------------------------	-------------------------	--------------	---	--------------------------------

				INCORRECT FTL BOUNDARY DEMARCATIONS; AYACUT PARTS ENCROACHED BY GOONS; SEWERAGE INFLOWS; ENCROACHMENT BY DUMPING ROCKS & CONSTRUCTION COLONIES; RAIN WATER INFLOW BLOCKED	560/2013/B1				
12.	3737	Central University lake	Serilingampally RR			CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc			
13.	3746	UOH Pond	Serilingampally RR			CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc			
14.	3701	Central univ. lake, Peacock Lake	Serilingampally RR			CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc			
15.	3721	Buffalo lake – gundla	SerilingampallyRR			CRD, PS(RD), Collector,MRO, APPCB,			

SL NO	HMDA LAKE ID	NAME	Mandal & District	Nature of Complaint	Date Initiated/ Reminders	Authorities Responsible	Action Taken	Lat/Long coordinates for HMDA missing lakes	Complaints held up at - Agency
-------	--------------	------	-------------------	---------------------	---------------------------	-------------------------	--------------	---	--------------------------------

		kunta				HMDA, etc			
16.	3740	Crane lake	Serilingampally RR						
17.	3716	Neerla Cheruvu	Serilingampally, RR	ENCROACHMENTS BY CONSTRUCTIONS; SHRINKAGE OF LAKE; ANTI-LAKE MEASURES FOR 'BEAUTIFICATION'		CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc			Collector, MRO, HMDA
18.	3710	Gangaram Pedda Cheruvu	Serilingampally RR	ENCROACHMENTS IN LAKEBED & LAYOUTS		CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc			Collector, MRO, HMDA
19.	3724	Lingamkunta Lake/Deptishrinagar	Serilingampally RR			CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc			
20.	3715	Kotta Kunta	Serilingampally RR			CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc			
21.	3717	Tammidi Kunta	Serilingampally RR	ENCROACHMENT BY N-CONVENTION	3.7.2011 2815/2012/ B1	CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc			Collector, MRO, HMDA
22.	3759	Basupalli	Serilingampally RR			CRD, PS(RD), Collector,MRO,			

SL NO	HMDA LAKE ID	NAME	Mandal & District	Nature of Complaint	Date Initiated/ Reminders	Authorities Responsible	Action Taken	Lat/Long coordinates for HMDA missing lakes	Complaints held up at - Agency
-------	--------------	------	-------------------	---------------------	---------------------------	-------------------------	--------------	---	--------------------------------

		Cheruvu				APPCB, HMDA, etc			
23.	3707	Malka Cheruvu	Serilingampally, RR	ENCROACHMENT BY CONSTRUCTIONS; SEWERAGE INFLOWS INTO STORM WATER CHANNEL; FISHERMENS' LIVELIHOOD DISTURBED	19.11.2013	CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc			Collector, MRO, HMDA
24.	3754	Maska Kunta	Serilingampally, RR	CONSTRUCTION DEBRIS DUMPING; CONSTRUCTION OF WALL; GARBAGE DUMPING SEWERAGE INFLOWS;	24.10.2013	CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc			Collector, MRO, HMDA
25.	3729	Kaidamma Kunta	Serilingampally RR	GIANT WEEDS FILLED LAKE; CONSTRUCTION DEBRIS & GARBAGE DUMPING; SEWERAGE INFLOWS	24.10.2013	CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc			Collector, MRO, HMDA
26.	3722	Meedi Kunta	Serilingampally	JCB DIGGING IN LAKE BED; HEAVY CONSTRUCTION DEBRIS DUMPING; LITIGATIONAL CONSTRUCTIONS;	24.10.2013	CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc			Collector, MRO, HMDA
27.	3703	Ranganna Kunta	Serilingampally RR	INFLOW BLOCKED-ENCROACHED; GHMC GARBAGE POINT; ENCROACHMENT TEMPLE	24.10.2013	CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc			Collector, MRO, HMDA

SL NO	HMDA LAKE ID	NAME	Mandal & District	Nature of Complaint	Date Initiated/ Reminders	Authorities Responsible	Action Taken	Lat/Long coordinates for HMDA missing lakes	Complaints held up at - Agency
-------	--------------	------	-------------------	---------------------	---------------------------	-------------------------	--------------	---	--------------------------------

				& SHOPS; OUTFLOW CONCRETIZED					
28.	3706	Durgam cheruvu	Serilingampally, RR	SLUICES OPENED FOR WATER DRAINAGE; ENCROACHMENT – APARTMENT COMPLEXES; SEWERAGE INFLOWS FROM APARTMENTS; CONSTRUCTION IN LAKEBED APTDC;	03.08.2013	CRD, PS(RD), Collector, MRO, APPCB, HMDA, etc			APTDC, HMWSSB, CE-MI, APPCB, GHMC, HMDA
29.	3711	Gurunath Cheruvu	Serilingampally RR			CRD, PS(RD), Collector, MRO, APPCB, HMDA, etc			
30.	3756	Kalapuram Basthi Kunta	Serilingampally RR			CRD, PS(RD), Collector, MRO, APPCB, HMDA, etc			
31.	3731	Erla Cheruvu (Madinaguda)	Serilingampally RR	DUPLEX HOUSES IN FTL; PERMITTED BY GHMC	06.09.2010; 1715/2012/B1	CRD, PS(RD), Collector, MRO, APPCB, HMDA, etc			GHMC; COLLECTOR; MRO
32.	3744	Kondapa	Serilingampally						

SL NO	HMDA LAKE ID	NAME	Mandal & District	Nature of Complaint	Date Initiated/ Reminders	Authorities Responsible	Action Taken	Lat/Long coordinates for HMDA missing lakes	Complaints held up at - Agency
-------	--------------	------	-------------------	---------------------	---------------------------	-------------------------	--------------	---	--------------------------------

		ur Forest Lake	lly RR						
33.	3748	KBR Lake	Serilingampalily RR			CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc			
34.	3758	Camlet Layout Lake	Serilingampalily RR			CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc			
35.	3742	Gautami Lake-Kudakunta	Serilingampalily RR			CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc			
36.	3752	Masjid Banda Lake	Serilingampalily RR			CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc			
37.	3739	Pochamma Lake	Serilingampalily RR			CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc			
38.	3736	Sudarshan Lake	Serilingampalily RR			CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc			
39.	3714	Gopi	Serilingampa	RAJIV SWAGRUHA IN		CRD, PS(RD),			Collector,

SL NO	HMDA LAKE ID	NAME	Mandal & District	Nature of Complaint	Date Initiated/ Reminders	Authorities Responsible	Action Taken	Lat/Long coordinates for HMDA missing lakes	Complaints held up at - Agency
-------	--------------	------	-------------------	---------------------	---------------------------	-------------------------	--------------	---	--------------------------------

		Cheruvu	lly RR	BETWEEN GOPI AND CHAKALA CHERUVU SEE 3722		Collector,MRO, APPCB, HMDA, etc			MRO, HMDA
40.	3728	Medla Kunta-Devuni Kunta	Serilingampally RR	COMPOUND WALL AND LAND FILLING IN FTL	MSG FROM JANAM KOSAM	CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc	EE/NT D/1159 DT.4.7. 2013		Collector, MRO, HMDA
41.	3723	Meedi Kunta-Opp Wipro	Serilingampally RR	FILLING OF LAKE BY WIPRO	26.062008 1914/2012/B1	CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc	JOINT INSPECTION 12.1.13		Collector, MRO, HMDA
42.	3734	Ramant ha Cheruvu - Opp Meghan a College	Serilingampally RR		3791/2012/B1	CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc			
43.	3747	Komati Kunta	SerilingampallyRR			CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc			
44.	3704	Medla Cheruvu tellapur	SerilingampallyRR	ALIENS SPACE STATION APARTMENTS IN LAKE WITH HMDA PERMISSION	MEETING WITH SUNIL GUPTA	CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc			Collector, MRO, HMDA
45.	3718	Pedda	SerilingampallyRR			CRD, PS(RD),			

SL NO	HMDA LAKE ID	NAME	Mandal & District	Nature of Complaint	Date Initiated/ Reminders	Authorities Responsible	Action Taken	Lat/Long coordinates for HMDA missing lakes	Complaints held up at - Agency
-------	--------------	------	-------------------	---------------------	---------------------------	-------------------------	--------------	---	--------------------------------

		Kudi Kunta-MAkta Kindi Kunta	IlyRR			Collector,MRO, APPCB, HMDA, etc			
46.	3755	BK Enclave Lake-makta meedi kunta Adjacent to Miyapur Bus Depot	SerilingampalIlyRR		2647/2012/B1	CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc			Collector, MRO, HMDA
47.	3700	Chanda Nagar Mallayya Kunta Adj to huda colony	SerilingampalIlyRR			CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc			
48.	3719	Chakali Vani Kunta	SerilingampalIlyRR	RAJIV SWAGRUHA CONSTRUCTIONS; ROAD IN LAKE; DUMPING	3509/2012/B1 DT.11.2.20	CRD, PS(RD), Collector,MRO, APPCB,			Collector, MRO, HMDA

SL NO	HMDA LAKE ID	NAME	Mandal & District	Nature of Complaint	Date Initiated/ Reminders	Authorities Responsible	Action Taken	Lat/Long coordinates for HMDA missing lakes	Complaints held up at - Agency
-------	--------------	------	-------------------	---------------------	---------------------------	-------------------------	--------------	---	--------------------------------

		Sy No 54		WASTE; ENCROACHMENT	13 460/2013; WPMP 12937/2009 DT 13/5/2009	HMDA, etc			
49.	3702	Chinna Pedda Cheruvu	SerilingampallyRR			CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc			
50.	3732	Khanam et cheruvu	SerilingampallyRR			CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc			
51.	3730	Pedda cheruvu – Khajaguda cheruvu	Serilingampally RR	DUMPING OF STONES FROM STONE CRUSHER ON HILLTOP; CONSTRUCTION OF WALL INSIDE THE LAKE; ENCROACHMENT OF BUFFER ZONE & FTL FOR LAYING ROADS	4.7.2011	CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc			Collector, MRO, HMDA
52.	3726	Ramama Kunta	Serilingampally RR	ENCROACHMENT BY YSR NATIONAL INSTITUTE – HUGE LAND FILLING -		CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc			Collector, MRO, HMDA
53.	3715	Kotha cheruvu	SerilingampallyRR			CRD, PS(RD), Collector,MRO,			

SL NO	HMDA LAKE ID	NAME	Mandal & District	Nature of Complaint	Date Initiated/ Reminders	Authorities Responsible	Action Taken	Lat/Long coordinates for HMDA missing lakes	Complaints held up at - Agency
-------	--------------	------	-------------------	---------------------	---------------------------	-------------------------	--------------	---	--------------------------------

		kunta				APPCB, HMDA, etc			
54.	2735	Kapra lake-Oora Cheruvu	Kesara,RR	BUND/ROAD IN LAKEBED ACROSS NORTH TO SOUTH; CARNIVAL BADMINTON & VASISHTA TENNIS ACADEMY IN FTL; REAR PORTION OF SSENCLAVE IN FTL; ILLEGAL PLOTTING – DATA EROSION IN LAND RECORDS; GANESHA IMMERSION FACILITY BY DUMPING; EESHWARI COLONY IN LAKEBED;	30.08.2013	CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc			Collector, MRO, HMDA
55.	2842	Mondi Kunta 2877/20 12/B1	Qutubullapur RR	NALA ENCROACHMENT BY HIGHRISES; INFLOWS BLOCKED; GARBAGE & CONSTRUCTION DEBRIS DUMPING;	Lokayukta 2877/2012/B1	CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc			Collector, MRO, HMDA
56.	2821	Pedda Kunta/ Maddela kunta	Qutubullapur RR,	SHRINKAGE OF LAKE - RESIDENTS REPRESENTATION TO PROTECT LAKE	9.7.2012	CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc			Collector, MRO, HMDA
57.	2823	Meddi Kunta	Qutubullapur , RR	REAL ESTATE ENCROACHMENT SOUTH OF LAKE; GIANT WATER WEEDS; GARBAGE &		CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc			Collector, MRO, HMDA

SL NO	HMDA LAKE ID	NAME	Mandal & District	Nature of Complaint	Date Initiated/ Reminders	Authorities Responsible	Action Taken	Lat/Long coordinates for HMDA missing lakes	Complaints held up at - Agency
-------	--------------	------	-------------------	---------------------	---------------------------	-------------------------	--------------	---	--------------------------------

				CONSTRUCTION DUMPING; ENCROACHMENT; SEWERGE INFLOWS;					
58.	2879	Nizamp et Cheruvu	Qutubullapur RR	DUMPING FROM ROAD SIDE; HYACINTH GROWTH;		CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc			Collector, MRO, HMDA
59.	2847	Papayya Kunta	Qutubullapur RR			CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc			
60.	2849	Dastagin Kunta	Qutubullapur RR			CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc			
61.	2839	Fox Sagar	Qutubullapur RR	ENCROACHMENT; PLOTTING;	2.9.2010	CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc			Collector; MRO; HMDA
62.	4802	Ambeer Cheruvu	Balanagar RR	CONSTRUCTIONS IN FTL WITH HMDA PERMISSION; DUMPING CONSTRUCTION DEBRIS; SEWERAGE INFLOW FROM SURROUNDING RESIDENTIALS; GARBAGE BURNING & DUMPING IN	16.07 2012;	CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc			Collector, MRO, HMDA

SL NO	HMDA LAKE ID	NAME	Mandal & District	Nature of Complaint	Date Initiated/ Reminders	Authorities Responsible	Action Taken	Lat/Long coordinates for HMDA missing lakes	Complaints held up at - Agency
-------	--------------	------	-------------------	---------------------	---------------------------	-------------------------	--------------	---	--------------------------------

				LAKE BED; RELIGIOUS CONSTRUCTION IN LAKE BED; SEWERAGE POINTS INSIDE LAKE FENCE; IRREGULAR LAKE FENCING;					
63.	4806	Kindikunta S.No. 188&189	Balanagar RR	SEWERAGE & ENCROACHMENT		CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc			Collector, MRO, HMDA
64.	4810	Yellamma Cheruvu	Balanagar RR	MULTIPLE FTL MAPS; CONSTRUCTION MY RAMKY IN SURVEY NOS. BANNED BY HC ORDER; SEWERAGE INFLOWS; GIANT WEEDS; GHMC GARBAGE BINS IN LAKE BED; WEIR BROKEN; GARBAGE BURNING IN LAKE BED; SANCTION OF BUILDING PERMISSION IN LAKE BEDS; REPEATED REPRESENTATIONS BY LOCALS IGNORED;	26.7.2011; 10.12.2013	CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc			Collector, MRO, HMDA
65.	4814	Yellamma	Balanagar, RR	IRREGULAR FTL BOUNDARY		CRD, PS(RD), Collector,MRO,			GHMC; MRO;

SL NO	HMDA LAKE ID	NAME	Mandal & District	Nature of Complaint	Date Initiated/ Reminders	Authorities Responsible	Action Taken	Lat/Long coordinates for HMDA missing lakes	Complaints held up at - Agency
-------	--------------	------	-------------------	---------------------	---------------------------	-------------------------	--------------	---	--------------------------------

		kunta		DEMARCATIONS; SEWERAGE INFLOWS; REPEATED REPRESENTATIONS BY LOCALS IGNORED;		APPCB, HMDA, etc			COLLECTOR
66.	4801	Pariki cheruvu	Balanagar RR	ROAD CUTTING THE LAKE; BOULDERS DUMPED IN LAKE; GIANT WEEDS; MISLEADING SNOS. PAINTED ON ROCKS; GRAVEYARD; CONSTRUCTION DEBRIS DUMPING NEAR JNNURM HOUSES; ROCK QUARRYING;		CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc			Collector, MRO, HMDA
67.	4811	Bheemu ni Kunta	Balanagar RR			CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc			
68.	4800	Chinna maisamma cheruvu	Balanagar RR			CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc			
69.	4803	Khajakunta	Balanagar RR	ENCROACHMENTS		CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc			

SL NO	HMDA LAKE ID	NAME	Mandal & District	Nature of Complaint	Date Initiated/ Reminders	Authorities Responsible	Action Taken	Lat/Long coordinates for HMDA missing lakes	Complaints held up at - Agency
-------	--------------	------	-------------------	---------------------	---------------------------	-------------------------	--------------	---	--------------------------------

70.	4808	Rangadh amuni kunta-idl cheruvu	Balanagar RR	DUMPING OF HUGE BOULDERS & DEBRIS; ENCROACHMENTS; STRUCTURES IN FTL BOUNDARIES		CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc			
71.	4809	Nalla cheruvu (kukatpally lake)	Balanagar RR	ENCROACHMENTS		CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc			
72.	4816	Botanical garden Lake	Balanagar RR	EROSION OF LAKE DUE TO ROAD WIDENING; WATER DRAINED OUT FROM LAKE BY GOVT. AUTHORITIES	HRCPC DT.7.12.2013; 2.1.2014	CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc			Collector, MRO, HMDA
73.	4804	Kamuni Cheruvu Balanagar	Balanagar, RR	PLOTTING IN BUFFER ZONE; BROKEN SURPLUS WEIR;		CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc			Collector, MRO, HMDA
74.	4807	Mundlakatwa cheruvu	Balanagar RR	KACHA ROAD IN LAKE BED; FLYOVER, RLY LINE IN FTL; MANIPULATION OF SURPLUS WEIR; HEAVY WATER OUTFLOW; FTL FILLED WITH DEBRIS & BOULDERS		CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc			Collector, MRO, HMDA
75.	4812	BOIN CHERUVU(Has	Balanagar, RR	ENCROACHMENT BY APARTMENTS & INDEPENDENT HOUSES;	30.07.2012	CRD, PS(RD), Collector,MRO, APPCB,			CNC, MI; GHMC; COLLECTOR

SL NO	HMDA LAKE ID	NAME	Mandal & District	Nature of Complaint	Date Initiated/ Reminders	Authorities Responsible	Action Taken	Lat/Long coordinates for HMDA missing lakes	Complaints held up at - Agency
-------	--------------	------	-------------------	---------------------	---------------------------	-------------------------	--------------	---	--------------------------------

		mathpet lake)		DESTRUCTION OF WEIR; SEWERAGE POLLUTION;		HMDA, etc			,RR
76.	3802	Chinna Cheruvu	Uppal, RR	19.8 acres SHRUNK TO 10 ACRES; OUTFLOWS & INFLOWS DIVERTED; LINK BETWEEN PEDDA & CHINNA CHERUVU BROKEN; GARBAGE MUD DUMPING; GHMC RTI REPLY AS ENCROACHMENT BY 2 TEMPLES; PLANNING FOR ANOTHER TEMPLE; SEWERAGE INFLOWS;	17.09.2011; 2010	CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc			Collector, MRO, HMDA
77.	3811	Ramant hapur cheruvu	Uppal RR	33ACS. LAKE SHRUNK TO 10 ACS DRY LAND; 22LACS ALLOTTED FOR FENCING- NO FENCING DONE; ENCROACHMENT WITH RESIDENTIAL; INFLOWS DIVERTED TO MUSI; SEWERAGE INFLOWS; MANY CASES FILED;	2010	CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc			GHMC; MRO, COLLECTOR ;
78.	3803	Nalla Cheruvu	Uppal RR	ROAD ENCROACHMENT; SEWERAGE WATER INFLOWS;	2010	CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc			Collector, MRO, HMDA
79.	3815	Mohini	Uppal, RR	BUILDING		CRD, PS(RD),			Collector,

SL NO	HMDA LAKE ID	NAME	Mandal & District	Nature of Complaint	Date Initiated/ Reminders	Authorities Responsible	Action Taken	Lat/Long coordinates for HMDA missing lakes	Complaints held up at - Agency
-------	--------------	------	-------------------	---------------------	---------------------------	-------------------------	--------------	---	--------------------------------

		Cheruvu		ENCROACHMENT; SEWERAGE INFLOWS;		Collector,MRO, APPCB, HMDA, etc			MRO, HMDA
80.	3801	Bandlag uda cheruvu	Uppal RR	SOLID/LIQUID/DEBRIS DUMPING -		CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc			Collector, MRO, HMDA
81.	1960	Kappala Cheruvu	Hayatnagar RR	SEWERAGE INFLOWS THRU INLET CHANNELS; SHRINKAGE OF LAKE; THREAT TO GREEN ZONE ON SHORES OF LAKE; GARBAGE & CONSTRUCTION DEBRIS DUMPING;		CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc			Collector, MRO, HMDA
82.	2386	Kamuni cheruvu, shamsha bad	Shamshabad RR	POWER SUBSTATION IN MIDDLE OF LAKE; 8 ACRES OF LAKE BED ENCROACHED; WALL UNDER CONSTRUCTION IN LAKEBED; GARBAGE PILE IN LAKE BED; RAINWATER INFLOWS BLOCKED;	28.3.2013	CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc			CE-MI; GHMC
83.	4700	RK Puram-	Malkajgiri RR	CONSRUCTION ENCROACHMENTS;		CRD, PS(RD), Collector,MRO,			Collector, MRO,

SL NO	HMDA LAKE ID	NAME	Mandal & District	Nature of Complaint	Date Initiated/ Reminders	Authorities Responsible	Action Taken	Lat/Long coordinates for HMDA missing lakes	Complaints held up at - Agency
-------	--------------	------	-------------------	---------------------	---------------------------	-------------------------	--------------	---	--------------------------------

		Mukkidi Cheruvu				APPCB, HMDA, etc			HMDA
84.	4707	kotha cheruvu	Malkajgiri, RR	ENCROACHMENT IN FTL & BUFFER ZONE; IRREGULAR DEMARCATION; ENCROACHMENT BY RESIDENTIAL COLONIES; DUMPING	11.11.2007.	CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc			MRO, GHMC
85.	4708	Chinnarayan Cheruvu	Malkajgiri, RR	ENCROACHMENT IN FTL & BUFFER ZONE; IRREGULAR DEMARCATION; ENCROACHMENT BY RESIDENTIAL COLONIES; DUMPING	11.11.2007	CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc			MRO, GHMC
86.	2428	Kothwal Cheruvu	Maheshwaram RR						
87.	2920	Shikham Cheruvu (alkapur manikon da)	Rajendranagar,RR	SEWERAGE INFLOWS IN LAKE; SERIOUS THREAT TO BIODIVERSITY OF LAKE; ENCROACHMENTS FROM MAINROAD ABUTTING THE LAKE.	Oral petitions Sep.2013-4.1.2014	CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc			Collector, MRO, HMDA
88.	2949	Shadham Talab	Rajendranagar RR	ENCROACHMENT BY RESIDENTIAL BLDGS.; HYDERABAD GOLF ASSOCIATION OFFICE IN FTL AND ENCROACHMENT		CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc			Collector, MRO, HMDA

SL NO	HMDA LAKE ID	NAME	Mandal & District	Nature of Complaint	Date Initiated/ Reminders	Authorities Responsible	Action Taken	Lat/Long coordinates for HMDA missing lakes	Complaints held up at - Agency
-------	--------------	------	-------------------	---------------------	---------------------------	-------------------------	--------------	---	--------------------------------

				BY DUMPING; CONSTRUCTION OF SPILWAY IN THE LAKEBODY BY GHMC					
89.	2907	Osman sagar	Rajendranaga r,RR	51 VIOLATIONS ALONG THE MAXIMUM WATER SPREAD AT FTL; VIOLATION OF GO111 – POLLUTIONS;		CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc			Collector, MRO, HMDA
90.	2919	Himayat h Sagar	Rajendranaga r, RR	91 VIOLATIONS ALONG THE MAXIMUM WATER SPREAD AT FTL; VIOLATION OF GO111 – POLLUTIONS;		CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc			Collector, MRO, HMDA
91.	2943	Palle Cheruvu -Oora Cheruvu	Rajendranaga r RR	HINDU FLAG IN FTL; OUTFLOW DEEPENED FOR WATER DRIANAGE; GARBAGE DUMPING; ENCROACHMENT CONSTRUCTION OF WALL AND HOUSES IN FTL;		CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc			Collector, MRO, HMDA
92.	2941	Marsha Bhai Kunta	Rajendranaga r RR	HINDU GRAVEYARD; SEWERAGE INFLOW; SEPTIC TANK IN LAKE BED;		CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc			Collector, MRO, HMDA
93.	2950	Pedda Talli Kunta	Rajendranaga r,RR	DUMPING MUD & GARBAGE; SEWERAGE INFLOWS; OUTFLOW CHANNEL BLOCKED		CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc			Collector, MRO, HMDA

SL NO	HMDA LAKE ID	NAME	Mandal & District	Nature of Complaint	Date Initiated/ Reminders	Authorities Responsible	Action Taken	Lat/Long coordinates for HMDA missing lakes	Complaints held up at - Agency
-------	--------------	------	-------------------	---------------------	---------------------------	-------------------------	--------------	---	--------------------------------

94.	2928	Sulaiman Cheruvu / Shilan Cheruvu /Sultan talab	Rajendranagar,RR	HINDU GRAVEYARD; SEWERAGE INFLOW; HINDU SHMASHAN GHAT;		CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc			Collector, MRO, HMDA
95.	2952	Noor Mohamed Kunta	Rajendranagar, RR	OUTFLOW DRIANAGE; HINDU-MUSLIM GRAVEYARD; ENCROACHMENT BY STP; INDUSTRIAL POLLUTION INFLOW; SOLID WASTE-MECHANICAL SHOP		CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc			Collector, MRO, HMDA
96.	2935	Huda Park lake/ Rukun-Ud-Dowla talab	Rajendranagar RR	PLASTIC WASTE BY PLASTIC INDUSTRIES; SEWERAGE INFLOWS; ENCROACHMENT; BUND BROKEN; CONSTRUCTIONS IN FTL;	14.1.2013 NOVEMBER 2013	CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc			Collector, MRO, HMDA
97.	2951	Palle Cheruvu	Rajendranagar,RR	DUMPING OF PLASTIC & SOLID WASTE; ENCROACHMENT BY DUMPING MUD & CONSTRUCTION HOUSES; SEWERAGE INFLO;	5.4.2013	CRD, PS(RD), Collector,MRO, APPCB, EE(IRR) HMDA, etc			Collector, MRO, HMDA

SL NO	HMDA LAKE ID	NAME	Mandal & District	Nature of Complaint	Date Initiated/ Reminders	Authorities Responsible	Action Taken	Lat/Long coordinates for HMDA missing lakes	Complaints held up at - Agency
-------	--------------	------	-------------------	---------------------	---------------------------	-------------------------	--------------	---	--------------------------------

				PRIVATE GARDEN; DUMPING MUD & ROCKS; WATER INLET BLOCKED; WATER OUTFLOW THRU PIPELINE;					
98.	2924	Bhagirat hamma Cheruvu Khajaguda Lake- NAnakramguda Village,	Rajendranagar RR	CEMENT ROAD BY GHMC IN FTL; OTHER ENCROACHMENTS	31.64/2012	CRD, PS(RD), Collector, MRO, APPCB, HMDA, etc			Collector, MRO, HMDA
99.	2926	Muskini cheruvu	Rajendranagar RR	GO419 DT 13.09.2013 FOR CHANGE OF LAND USE FROM WATER BODY TO MULTIPLE USE; ADJACENT OSMANSAGAR CANALS SENSITIVITY IGNORED; PREVIOUS GOVT REPORTS & PLANS OVERRIDED;	30.12.2013	CRD, PS(RD), Collector, MRO, APPCB, IRR. AUTHORITIES HMDA, etc			Collector, MRO, HMDA
100	2923	Yellamma cheruvu/ manikon da jagir cheruvu	Serilingampally, RR	CONSTRUCTION IN LAKEBED WITHOUT PERMISSION OF SOUTH ASIA'S LARGEST MALL – DUMPING FOR ROAD IN LAKEBED; IRREGULAR FTL	26.04.2013 SUO MOTO CASE OF LOKAYUKTA	CRD, PS(RD), Collector, MRO, APPCB, HMDA, etc			Collector, MRO, HMDA

SL NO	HMDA LAKE ID	NAME	Mandal & District	Nature of Complaint	Date Initiated/ Reminders	Authorities Responsible	Action Taken	Lat/Long coordinates for HMDA missing lakes	Complaints held up at - Agency
-------	--------------	------	-------------------	---------------------	---------------------------	-------------------------	--------------	---	--------------------------------

				DEMARCATIION & FENCING; DESTRUCTION OF WEIR	867/201/B1				
101	3709	Miyapur Patel Cheruvu Miyapur -Nalla Connecting patel and Gangaram Cheruvu	Serilingampally, RR	ILLEGAL CONSTRUCTION OF MULTI-STOREYED BLDG ON TOP OF NALA; ENCROACHMENT ALL AROUND BY RESIDENTIAL COMPLEXES	7.5.2011	CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc	HC ORDER TO DEMOLISH BUILDING	17°29'48.99"N 78°21'3.09"E	GHMC, COLLECTOR, MRO
102	2640	Judar Cheruvu	Ghatkesar RR	SEVERE HYACINTH GROWTH; SERIOUS THREAT TO BIODIVERSITY;		CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc			Collector, MRO, HMDA
103	4001	Noorisha Talab/ Sikam Cheruvu	Bandlaguda, Hyd	ENCROACHMENT BY DUMPING; CONSTRUCTION OF HOUSES; SEWERAGE INFLOWS; TEMPLE ON BUND;	5.4.2013	CRD, PS(RD), Collector,MRO, APPCB, EE(IRR) HMDA, etc			Collector, MRO, HMDA
104	4000	Balapur Talab/ Gurram cheruvu	Bandlaguda, Hyd	SEWERAGE INFLOWS; ENCROACHMENT BY DUMPING MUD & SOLID WASTE; DUMPING YARD	5.4.2013	CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc			Collector, MRO, HMDA
105	4400	Mir	Bahadurpura,	SEWERAGE INFLOWS;		CRD, PS(RD),			Collector,

SL NO	HMDA LAKE ID	NAME	Mandal & District	Nature of Complaint	Date Initiated/ Reminders	Authorities Responsible	Action Taken	Lat/Long coordinates for HMDA missing lakes	Complaints held up at - Agency
-------	--------------	------	-------------------	---------------------	---------------------------	-------------------------	--------------	---	--------------------------------

		Alam Tank	Hyd	DUMPING OF WASTE; ENCROACHMENT THRU GRAVEYARD -HUDA PARK - TEMPLE; SEWERAGE LINES CONNECTED TO LAKE ; PLASTIC INDUSTRIES WASTE INFLOWS; MECHANICAL SHOP OUTFLOWS;		Collector,MRO, APPCB, HMDA, etc			MRO, HMDA
106	4101	Hussain sagar	Khairtabad HYD	AROUND 50 SERIOUS VIOLATIONS AROUND 'HEART OF THE WORLD' LAKE; ENCROACHMENTS AGAINST SC & HC ORDERS; UNVIABLE DREDGING AGAINST SC COMMT REPORT; CHEMICAL EFFLUENTS & 24/7 SEWERAGE; FOUL SMELL AFFECTING HEALTH OF TOURISTS;		CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc			Collector, MRO, HMDA
107	3906	Shahata m talab	Shaikpet Hyd			CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc			
108	3904	Jamali Kunta	Shaikpet Hyd	ENCROACHMENT BY HYDERABAD GOLF		CRD, PS(RD), Collector,MRO,			Collector, MRO,

SL NO	HMDA LAKE ID	NAME	Mandal & District	Nature of Complaint	Date Initiated/ Reminders	Authorities Responsible	Action Taken	Lat/Long coordinates for HMDA missing lakes	Complaints held up at - Agency
-------	--------------	------	-------------------	---------------------	---------------------------	-------------------------	--------------	---	--------------------------------

				COURSE; LAKE SHRUNK BY 85%;		APPCB, HMDA, etc			HMDA
109	3900	Anantagani kunta/Banjara LAKE	Shaikpet, Hyd	ENCROACHMENT BY BANJARA HOTEL, GHMC & PRIVATE BUILDERS; POLLUTION FROM BANJARA NALA; DUMPING BY GHMC & HMWSSB & TAJ BANJARA	29.11.2010	CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc			GHMC & HMWSSB
110	3903	Hakimpet cheruvu	Shaikpet, HYD	TEMPLE JUTTING IN LAKE; SEWERAGE INFLOWS; FRESH DEBRIS BEING DUMPED DAILY;	26.04.2011	CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc			GHMC;
111	4200	Ramanna Cheruvu	Tirumalgiri Hyd	ENCROACHMENT; LAKE OVERFLOWING ON ROADS WITH SEWERAGE;		CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc			Collector, MRO, HMDA
112	5000	Saroornagar lake	Saidabad, Hyd	SINGARENI COLLARIES CONSTRUCTIONS IN LAKEBED; HEAVY CONSTANT SEWERAGE INFLOW;	22.09.2010 21.12.2011	CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc		17°21'16.01"N 78°31'37.54"E	Collector, MRO, HMDA
113	120/45	BHEL TOWNSHIP Lake(Beerangud	Pathancheruvu, Medak	DUMPING OF PLASTIC & E-WASTE; ENCROACHMENT RELIGIOUS STRUCTURE; HYACINTH GROWTH;		CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc			Collector, MRO, HMDA

SL NO	HMDA LAKE ID	NAME	Mandal & District	Nature of Complaint	Date Initiated/ Reminders	Authorities Responsible	Action Taken	Lat/Long coordinates for HMDA missing lakes	Complaints held up at - Agency
-------	--------------	------	-------------------	---------------------	---------------------------	-------------------------	--------------	---	--------------------------------

		a lake)							
114	1590	Mahboob Sagar/ Terrakunta S.No-180/193	SangaReddy Medak	BUND CONSTRUCTED INSIDE LAKE;		CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc			Collector, MRO, HMDA
115	1537	Patha Cheruvu Shikam	Sangareddy Medak	REAL ESTATE LAYOUT IN FTL BOUNDARIES		CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc			Collector, MRO, HMDA
116	1200/42	Ameenpur ChinNa Cheruvu	Pathancheruvu Medak	ROCK QUARRYING AFFECTING BIO-DIVERSITY ESPECIALLY BAT COLONIES; LAKE SHRINKAGE;		CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc			Collector, MRO, HMDA
117	1200/51	Beeramguda Lake	Pathancheruvu Medak			CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc			
118	606	Raisamudram(BHEL townshi	Ramchandra puram, Medak	SEWERAGE LINES WITHOUT STP; GHMC DUMPING OF GARBAGE; HYACINTH GROWTH;		CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc			Collector, MRO, HMDA

SL NO	HMDA LAKE ID	NAME	Mandal & District	Nature of Complaint	Date Initiated/ Reminders	Authorities Responsible	Action Taken	Lat/Long coordinates for HMDA missing lakes	Complaints held up at - Agency
-------	--------------	------	-------------------	---------------------	---------------------------	-------------------------	--------------	---	--------------------------------

		p lake)		POSSIBLE ENCROACHMENT;dysfunctional STP					
119	1200/34	Ameenpur-Pedda Cheruvu	Pathancheruvu Medak	STONE WALL & PATHWAY CONSTRUCTED; TEMPLE INSIDE LAKE; EXTENSIVE PLOTTING; HISTORIC LAKE GATE TAMPERED; SEWERAGE INFLOWS; DRAWING OF WATER BY PRIVATE SOURCES; THREAT TO BIO-DIVERSITY & FISHING;		CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc			Collector, MRO, HMDA
120	SOI/field	Maddi Kunta	Saroornagar, RR	WATER DRIANAGE THRU CONSTRUCTED OUTFLOW CHANNEL; ENCROACHMENT BY DUMPING ROCKS	5.4.2013	CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc		78°27'4.418"E 17°18'9.037"N	Collector, MRO, HMDA
121	SOI/field	Yerra Kunta-Laxminagar	Saroornagar, RR	HINDU GRAVEYARD; SEWERAGE INFLOW; DUMPING GARBAGE & PLASTIC; BLOCKED INFLOW BY PLASTIC & GARBAGE	5.4.2013	CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc		17.30045671030 78.44366117520	Collector, MRO, HMDA
122	SOI/field	Jahangeerabad Talab	Saroornagar, RR	SEWERAGE INFLOW PIPELLINE; DUMPING ROCKS; ENCROACHMENT;	5.4.2013	CRD, PS(RD), Collector,MRO, APPCB,		17.31031982450 78.46110720550	Collector, MRO, HMDA

SL NO	HMDA LAKE ID	NAME	Mandal & District	Nature of Complaint	Date Initiated/ Reminders	Authorities Responsible	Action Taken	Lat/Long coordinates for HMDA missing lakes	Complaints held up at - Agency
-------	--------------	------	-------------------	---------------------	---------------------------	-------------------------	--------------	---	--------------------------------

				GRAVEYARD & TEMPLE;		HMDA, etc			
123	SOI/field	Pedda Cheruvu				CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc		17.29993107550 78.49731549730	
124	SOI/field	Abbushar e Talab Private				CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc		17.28283982320 78.47867995610	
125	SOI/field	AkkammaKunta				CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc		17.25486785430 78.46167761770	
126	SOI/HMDA Report	Zoo Park Lake	Rajendranagar RR Bahadurpura RR	PROTECTED		CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc		78°26'37.955" E 17°20'59.496" N	Collector, MRO, HMDA
127	HMDA/SOI	University Cheruvu				CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc		78°25'23.958" E 17°19'5.38"N	
128	Field/google	Pattikunta-Opp Mytas	Qutubullapur, RR	CONSTRUCTION ENCROACHMENT; ROAD SIDE DUMPING; GARBAGE; SEWERAGE INFLOWS;		CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc		17°31'28.33"N 78°22'21.44"E	Collector, MRO, HMDA

SL NO	HMDA LAKE ID	NAME	Mandal & District	Nature of Complaint	Date Initiated/ Reminders	Authorities Responsible	Action Taken	Lat/Long coordinates for HMDA missing lakes	Complaints held up at - Agency
-------	--------------	------	-------------------	---------------------	---------------------------	-------------------------	--------------	---	--------------------------------

		Hill valley		OUTFLOW INFLOW CHANNELS TAMPERED; GRAVE IN LAKEBED;					
129	google	Lake Behind Mytas Hill County				CRD, PS(RD), Collector, MRO, APPCB, HMDA, etc		17°31'31.21"N 78°22'35.94"E	
130	Field/ Google/	Rajanna Bowli	Bandlaguda, Hyderabad	HISTORIC BOWLI COVERED WITH GARBAGE; COMPOUND WALL COLLAPSE; THREAT OF CLOSURE DUE TO MOSQUITOES;		CRD, PS(RD), Collector, MRO, APPCB, HMDA, etc		17° 20' 25.80", 78° 28' 22.71	Collector, MRO, HMDA
131	Google/field	Ibrahim Cheruvu	Balanagar, RR	ENCROACHMENTS FROM MAINROAD ABUTTING THE LAKE.	Oral petitions Sep.2013-4.1.2014	CRD, PS(RD), Collector, MRO, APPCB, HMDA, etc		17°23'10.49"N 78°22'38.56"E	Collector, MRO, HMDA
132	Google/field visit	Botanical lake				CRD, PS(RD), Collector, MRO, APPCB, HMDA, etc		17°27'22.47"N 78°21'43.01"E	
133	Near 3728 Google/Field	Gopanally Nallakunta-MLA		ENCROACHMENT & CONSTRUCTIONS IN LAKE SNOS. 7-11,13, 14	1176/2010/B1 24.6.2013; CASE PENDING	CRD, PS(RD), Collector, MRO, APPCB, HMDA, etc		17°27'20.50"N 78°18'18.70"E	Collector, MRO, HMDA

SL NO	HMDA LAKE ID	NAME	Mandal & District	Nature of Complaint	Date Initiated/ Reminders	Authorities Responsible	Action Taken	Lat/Long coordinates for HMDA missing lakes	Complaints held up at - Agency
-------	--------------	------	-------------------	---------------------	---------------------------	-------------------------	--------------	---	--------------------------------

		grab lake			AT LGC				
134	Google /Field	Buchu Kunta Near Engineer Enclave				CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc		17°29'35.26"N 78°20'5.02"E	
135	Google Field visit	Lake Opp MAsjid banda Lake Near SBI office quarters Huda master plan				CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc		17°27'54.32"N 78°20'19.80"E	
136	Google /Field visit	Lingam kunta SNO_25 3, Chandanagar Village	Serinlingampally, RR	STP IN LAKE BED	1750/2010/B1 7 lakes WP 12727/2010	CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc		17°30'19.08"N 78°18'55.16"E	Collector, MRO, HMDA

SL NO	HMDA LAKE ID	NAME	Mandal & District	Nature of Complaint	Date Initiated/ Reminders	Authorities Responsible	Action Taken	Lat/Long coordinates for HMDA missing lakes	Complaints held up at - Agency
-------	--------------	------	-------------------	---------------------	---------------------------	-------------------------	--------------	---	--------------------------------

		Near Vemana Colony							
137	Google/Field visit	Mangalavani Kunta Adjacent to Hafeezpet			3789/2012	CRD, PS(RD), Collector, MRO, APPCB, HMDA, etc		17°28'59.98"N 78°21'27.62"E	
138	Google/Field Visit / state archives	Rukundowla Bowli	Rajendranagar, RR	ANIMAL CARCASSES & GARBAGE DUMPING AROUND BOWLI; HISTORIC VERY LARGE BOWLI NOT PROTECTED NOT LISTED;		CRD, PS(RD), Collector, MRO, APPCB, HMDA, etc		17°19'57.72"N 78°26'33.78"E	Collector, MRO, HMDA
139	Google/Field Visit	Unani Hospital Bowli	Charminar, Hyderabad	HISTORIC WELL WITH FRESH WATER; NOT MAINTAINED NOT LISTED;		CRD, PS(RD), Collector, MRO, APPCB, HMDA, etc		17° 21.626', 78° 28.521'	Collector, MRO, HMDA
140	Google/Field	EFLU Bowli, near Osmania		HUGE GARBAGE DUMPING; HISTORIC WELL NOT PROTECTED;		CRD, PS(RD), Collector, MRO, APPCB, HMDA, etc		17° 25.464', 78° 31.532'	Collector, MRO, HMDA

SL NO	HMDA LAKE ID	NAME	Mandal & District	Nature of Complaint	Date Initiated/ Reminders	Authorities Responsible	Action Taken	Lat/Long coordinates for HMDA missing lakes	Complaints held up at - Agency
-------	--------------	------	-------------------	---------------------	---------------------------	-------------------------	--------------	---	--------------------------------

	visit	Univ.							
141	Google /Field visit	Kanukunta - R.C.Puram				CRD, PS(RD), Collector, MRO, APPCB, HMDA, etc		17°29'59.39"N 78°18'49.33"E	
142	Google /Field visit	HUDA Stadium Grab Lake		SERIOUS ENCROACHMENT		CRD, PS(RD), Collector, MRO, APPCB, HMDA, etc		17°29'17.27"N 78°19'30.13"E	Collector, MRO, HMDA
143	SOI/HMDA	Shiva Nagar kunta	Rajendranagar, RR	DUMPING MUD; ENCROACHMENT; GARBAGE –PLASTIC WASTE DUMPING		CRD, PS(RD), Collector, MRO, APPCB, HMDA, etc		78°25'32.306"E 17°21'43.927"N	Collector, MRO, HMDA
144	SOI/HMDA	Kishan Bagh cheruvu	Rajendranagar, RR	APCPDCL SUBSTATION , SIKH CHOWNI AREA ENCROACHMENT; DUMPING GARBAGE & MUD;		CRD, PS(RD), Collector, MRO, APPCB, HMDA, etc		78°26'27.034"E 17°21'35.819"N	Collector, MRO, HMDA
145	SOI/HMDA Report	Krishna Nagar Tank	Rajendranagar, RR	DUMPING SOLID WASTE; INFLOW-OILY EFFLUENTS FROM MECHANICAL SHOPS		CRD, PS(RD), Collector, MRO, APPCB, HMDA, etc		78°25'40.005"E 17°22'4.943"N	Collector, MRO, HMDA
146	Field /Google	Naaram cheruvu/		PROTECTED - INSIDE ANGRAU		CRD, PS(RD), Collector, MRO,		17°18'48.77"N 78°24'50.71"E	Collector, MRO,

SL NO	HMDA LAKE ID	NAME	Mandal & District	Nature of Complaint	Date Initiated/ Reminders	Authorities Responsible	Action Taken	Lat/Long coordinates for HMDA missing lakes	Complaints held up at - Agency
-------	--------------	------	-------------------	---------------------	---------------------------	-------------------------	--------------	---	--------------------------------

	gle	kunta(in side angrau)				APPCB, HMDA, etc			HMDA
147	Field /Google	Bulbul kunta		SEWERAGE INFLOW; RELIGIOUS CONSTRUCTIONS; GARBAGE DUMPING;		CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc		17°18'28.00"N 78°26'55.81"E	Collector, MRO, HMDA
148	Google/field	Jalagam vengalra o park Lakebed of Enugula kunta SNO. 115/1	Khairatabad, Hyderabad	EXTENSIVE DUMPING OF MUD TO CREATE HINDU SHAMSHAN GHAT & KHABRASTAN INSPITE OF HIGH COURT ORDER IN WP 2347/2010 DT. 5.2.2010 SRDOI/3871/2009	18.03.2010	CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc		17°25'32.24"N 78°26'51.69"E	MAUD, GOAP; GHMC; Tahsildar, Khairatabad
149	Field /Google	Nayaqila talab; Langer houz	Golkonda, RR	SEWERAGE FROM SHAHTAM TALAB; SLUICES OPENED; CONTOURS BEING DISTURBED		CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc		17°23'20.71"N 78°24'34.77"E	APTDC; COLLECTOR ; SA,ASI HYDERABAD; EE-NT; MRO
150	Field / Google	Edulagutta	Shameerpet, RR	COMPLETE DESTRUCTION OF THE LAKE - POISONOUS LEACHATE & GARBAGE FROM JAWAHARNAGAR DUMPYARD	4.1.2014	GHMC; DISTRICT COLLECTOR; MRO; EE-ICAD		17°31'18.38"N 78°34'37.15"E	GHMC; DISTRICT COLLECTOR ; MRO; EE-ICAD

SL NO	HMDA LAKE ID	NAME	Mandal & District	Nature of Complaint	Date Initiated/ Reminders	Authorities Responsible	Action Taken	Lat/Long coordinates for HMDA missing lakes	Complaints held up at - Agency
-------	--------------	------	-------------------	---------------------	---------------------------	-------------------------	--------------	---	--------------------------------

151	Google Earth			Hindu news paper bandlaguda Cheruvu, ayappa Colony,Nagole		CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc			Collector, MRO, HMDA
152		Shamirpet lake	Shamirpet RR	LAKE POLLUTION THRU 'DEVELOPMENT' PLANS OF GOVERNMENT	5.9.2013 FBH	CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc			Collector, MRO, HMDA
153	Google/HUDA master plan	Pattikunta upstream (east of 2823)	Qutubullapur, RR			CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc		17°31'49.44"N 78°22'14.94"E	Collector, MRO, HMDA
154		Golnaka Nala, Musi river	Hyderabad	NALA ENCROACHMENT PLOTTING; NALA NEAR THE ENCROACHMENT CLOSED;		CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc		17°23'11.67"N 78°30'20.55"E	Collector, MRO, HMDA
155	Google/	Sunnam Lake	MLA MP Colony, Jubilee hills, Yousufguda	ENCROACHMENT		CRD, PS(RD), Collector,MRO, APPCB, HMDA, etc		17°26'31.42"N 78°25'0.96"E	

SL NO	HMDA LAKE ID	NAME	Mandal & District	Nature of Complaint	Date Initiated/ Reminders	Authorities Responsible	Action Taken	Lat/Long coordinates for HMDA missing lakes	Complaints held up at - Agency
-------	--------------	------	-------------------	---------------------	---------------------------	-------------------------	--------------	---	--------------------------------
